



1822 PINEHURST DR WEST PALM BEACH FL 33407

This report documents recorded construction activity related to this property as recorded by local permitting authorities, and includes information on contractors, potential risk factors, and other points of interest.

Property Summary

Below is a summary of the permit activity on this property.

Number of Permits:	5
Earliest Permit:	Nov 07, 1995
Latest Permit:	Feb 21, 2006
Total Cost of Work:	\$ 10,134.00
Unique Contractors:	4

The source for the data found in this report is the following Permitting Authority:

City of West Palm Beach, Construction Services 401 Clematis St., 1st Floor West Palm Beach, FL 33401 (561) 805-6700 Website: <u>www.cityofwpb.com</u>

The data received from this source runs consistently from Jan 01, 1990 through Jul 30, 2010. Information on construction activity occurring outside of this range may or may not be represented here.

Note: This report covers 2 property records. Permitting authorities sometimes provide BuildFax with multiple records for an individual property. Typically, this is the result of inconsistent forms of the address, e.g. MAIN ST vs MAIN STREET.

BY EVALUATING THE DATA CONTAINED ON THE SITE, THE EVALUATING PARTY AGREES TO BE BOUND BY THE TERMS OF USE AND ACKNOWLEDGES THAT SUCH AGREEMENT CONSTITUTES A BINDING CONTRACT BETWEEN THE EVALUATING PARTY AND BUILDERADIUS, DBA BuildFax.com.

Report Serial Number: 20101210102450566872-MVZRAK-258649



The data displayed here represents only that which has been received in digital format from available data source(s), and may not represent the totality of all data associated with searched properties. BuldFax is not responsible for omissions or inaccuracies. Information unavailable in digital format will not be represented.

Major Systems

In most communities, upgrading or installing one of the major systems in a house, listed below, calls for a permit. We search our database of nearly 100 Million permits to find major system records that pertain to the address you submitted.

Туре		Valuation	Latest Date	Jurisdiction Total
New Construction	No major Ne	w Construction work detected	d since Jan 01, 1990	3,039
Alteration/Remodel/Addition	~	\$ 4,500.00	Aug 07, 2001	31,144
Roof	\checkmark	\$ 4,500.00	Aug 07, 2001	29,910
Demolition	No major Demolition work detected since Jan 01, 1990			3,542
Building	No major Bu	No major Building work detected since Jan 01, 1990		
Electrical	~	\$ 250.00	Nov 07, 1995	54,052
Mechanical	~	\$ 2,985.00	Jul 02, 2003	28,875
Plumbing	No major Plumbing work detected since Jan 01, 1990			32,588
Pool	No major Po	ol work detected since Jan 01	1, 1990	10,048


Major Systems Details

Alteration/Remodel/Addition Associated permits - click to view details						
Number	•	Valuation	Date		Contractor	
01080291	ROOFING	\$4,500.00	Aug 07, 2001	LLOYDS RO	OFING CO INC	_
Roof As	sociated permit	s - click to view	details			
Number	Туре	Valuation	Date		Contractor	_
01080291	ROOFING	\$4,500.00	Aug 07, 2001	LLOYDS RO	OFING CO INC	
Electrical	Associated p	ermits - click to	view details			
Number		Туре	Valuation	Da	te Contractor	
95010401	ELECTRICA	L PERMIT	\$250.00	Nov 07, 19	95	
Mechanical	Associated	d permits - click	to view details			
Number		Туре	Valuation	Date	Contractor	
03070138	RESIDENTIAL CH	ANGE OUT ONL	Y \$2,985.00	Jul 02, 2003	Stephen K Denny Inc	

PermitHistory.com Report: 1822 PINEHURST DR WEST PALM BEACH FL 33407

Value

Permit documentation often contains a record of the value associated with the permitted construction. We search the BuildFax database of over \$3 Trillion dollars of documented work to find records that pertain to the address you submitted.



Value Details

Risk

BuildFax has developed a proprietary database of risk related permits that can indicate an INCREASE or DECREASE in the risk outlook for a property.

BuildFax Check™	Description	Trigger no ye	ed National s Frequency
Change of Use	Indication of whether work was done in connection with a change in use of the structure.	×	1/1000
Fire Alarm	Indication that work has been done on a fire alarm system.	×	4/1000
Fire Damage	Indication of whether work was done in response to damage caused by fire.	×	3/1000
Mobile Home	Indication of whether work was done on a manufactured home, mobile home, and/or temporary trailer.	×	17/1000
Natural Disaster Damage	Indication of whether work was done in response to damage caused by nature.	×	2/1000
Pests/Rodents	Indication of whether work was done in response to damage caused by pests or rodents.	×	1/1000
Repair/Replace	Indication of whether work was done to improve the functionality of the structure by repairing or replacing an existing feature.	`	83/1000
Security Systems	Indication that work has been done involving a security system / burglar alarm.	×	3/1000
Seismic Damage Prevention	Indication of whether work was done that would impact a structure's ability to withstand damage due to a seismic event.	×	1/1000
Solar Power	Indication of whether work was done that involved solar-powered heating and/or electricity.	×	1/1000
Sprinkler Systems	Indication of whether work was done involved a sprinkler system; excludes lawn sprinkler systems.	×	8/1000
Tank - No Septic	Indication of whether work was done involving a tank that is not a septic tank.	`	4/1000
Water Damage	Indication of whether work was done in response to damage caused by water.	×	1/1000
Wind Damage	Indication of whether work was done in response to damage caused by wind.	×	1/1000
Wind Damage Prevention	Indication of whether work was done that would impact a structure's ability to withstand damage due to a wind event.	×	2/1000

Risk Details

	whether work was done to improve the functionality of existing feature.	the structure by repairing or
Number	Description	Date
01080291	REROOF FIBERGLASS SHINGLES	Aug 07, 2001
heck: Tank ·	- No Septic	
Indication of Number	whether work was done involving a tank that is not a se	eptic tank. Date
05080918	install UG 500 LP Tank w/exterior/interi	Feb 21, 2006

Contractors

Below are the unique contractors detected to have worked on this property. Note that contractor permit counts and dates are unique to the reporting jurisdiction.

Contractor	Permits	Oldest	Latest
BRINKS HOME SECURITY	1716	Sep 29, 1998	Sep 22, 2009
FLORIDA PUBLIC UTILITIES CO	846	Oct 14, 1998	Jul 26, 2010
STEPHEN K DENNY INC	338	Sep 29, 1998	Jul 20, 2010
LLOYDS ROOFING CO INC	285	Sep 29, 1998	Jul 26, 2010

Contractor Details

Contractor: BR	INKS HOME SECURITY	
Maximum date:	Sep 22, 2009	
Minimum date:	Sep 29, 1998	
Permit count:	1716	
Contractor: FLC	ORIDA PUBLIC UTILITIES CO	
Maximum date:	Jul 26, 2010	
Minimum date:	Oct 14, 1998	
Permit count:	846	
Contractor: STE	PHEN K DENNY INC	
Maximum date:	Jul 20, 2010	
Minimum date:	Sep 29, 1998	
Permit count:	338	
Contractor: LLC	YDS ROOFING CO INC	
Maximum date:	Jul 26, 2010	
Minimum date:	Sep 29, 1998	
Permit count:	285	

Permits Below are the details on all permits found on this property. 1995 Permit #: 95010401 Permit Type: ELECTRICAL PERMIT Applied date: Nov 07, 1995 Permit status: Closed Issued date: Nov 07, 1995 Status date: Nov 07, 1995 Valuation amount: \$ 250.00 Inspections Туре **Result Description** Jan 26, 1996 ELECTRICAL FINAL Pass 2001 Permit #: 01080291 Permit Type: ROOFING Applied date: Aug 07, 2001 Description: **REROOF FIBERGLASS SHINGLES** Issued date: Aug 07, 2001 Status date: Aug 07, 2001 Permit status: Expired Valuation amount: \$ 4,500.00 Contractors LLOYDS ROOFING CO INC Inspections Туре Result Description Aug 09, 2001 ROOF SHEATHING Pass Aug 13, 2001 FINAL/CO Canceled 2003 Permit #: 03070138 Permit Type: RESIDENTIAL CHANGE OUT ONLY Applied date: Jul 02, 2003 Description: REPLACE EXISTING PACKAGE UNIT WITH Issued date: Jul 02, 2003 NEW, 10 KW 12 SEER D50SX042 Status date: Jul 02, 2003 Permit status: Closed Valuation \$ 2,985.00 amount: Contractors STEPHEN K DENNY INC

Inspections

Туре **Result Description** Aug 07, 2003 MECHANICAL FINAL Fail Aug 12, 2003 MECHANICAL FINAL Fail Aug 27, 2003 MECHANICAL FINAL Fail Sep 23, 2003 MECHANICAL FINAL Pass

Туре Jan 27, 2005 ELECTRICAL FINAL Pass

2004

Permit #: 041	11351				
Permit Type:	LOW VOLTAGE	Applied date: Nov 29, 2004			
Description:	INSTALL SECURITY SYS 1 MASTER 3	Issued date: Nov 29, 2004			
	DEVICES	Status date: Nov 29, 2004			
Permit status:	Closed				
Valuation	\$ 199.00				
amount:					
Contractors					
BRINKS HOME SECURITY					
Inspections					

Result Description

Date

Permit #: 05080918

Permit Type:GASDescription:install UG 500 LP Tank w/exterior/interiorValuation amount:\$ 2,200.00

Issued date: Feb 21, 2006 Status date: Feb 21, 2006

Contractors FLORIDA PUBLIC UTILITIES CO

Inspections

Date	Туре	Result	Description
Jan 24, 2006	LP TANK	Pass	
Jan 24, 2006	UNDERGROUND GAS	Pass	
Feb 10, 2006	ROUGH GAS	Fail	
Feb 13, 2006	ROUGH GAS	Pass	
Feb 21, 2006	FINAL GAS	Pass	

Report Help

Ten steps to understanding your BuildFax Structure PROFILE™

- 1. Verify the Address: Verify that the address printed above is correct, and if a map appears above the address, whether the map depicts the location of the address. This Structure PROFILE report is specifically for the address listed above.
- 2. Understand Coverage: BuildFax collects data from building departments through the United States and searches for your address, city, state, and zip within the data BuildFax collects. BuildFax considers the above address to be in coverage because either BuildFax has data from the specific municipality that the address is in, or BuildFax has data for the city, state, and zip code that the address is in and there is no separate city building department (meaning that the above address is permitted by either a county or a neighboring city). BuildFax provides a Structure PROFILE report for every address within coverage, regardless of whether BuildFax has individual building permits on the address, because knowing the age of major systems, lack of value increases, and absence of risk factors over time is critically valuable information on the address.
- 3. Note the Date Ranges: The "summary" tab lists two date ranges one for the building department ("jurisdiction") and one for the above address. The jurisdiction range covers the dates for which the full BuildFax database has data. This means that any permitted work within that date range on the above address will be listed in this Structure PROFILE. The address range covers the dates for which this Structure PROFILE has permits on the above address.
- 4. Know the Jurisdiction(s): The jurisdiction (also known as the building department, community development department, and/or permitting authority) listed on the "summary" tab is the source for the data within the Structure PROFILE. In the case where multiple jurisdictions have permits on the above address, you will see multiple jurisdictions as choices on tabs directly below the address above. BuildFax provides contact information for jurisdictions (including web sites where available) so that you can contact jurisdictions directly for further information.
- 5. Examine Major Systems: BuildFax organizes its knowledge of the jurisdiction's data and the specific address's data into several different views, one of which is an analysis of "major systems". BuildFax has identified a number of "major systems" for which (1) permits are overwhelmingly required, (2) jurisdictions store consistent information about the permits, and (3) if work is not permitted through the jurisdiction, it is a cause for concern. BuildFax is not perfect at its "major systems" analysis, but in recently-conducted controlled tests, the BuildFax analysis was correct more than 95% of the time. Because of the possibility of miscategorization or error, BuildFax encourages customers to contact the dedicated professionals at the relevant jurisdiction is something seems incorrect.
- 6. Break Down Value Changes: Another view that BuildFax provides into permit data is an analysis by permit valuation. Permit valuation is usually not the amount of money spent by the owner of the structure for the improvement or repair; rather, permit valuation is usually an estimate of construction cost, and, because it is usually used to estimate permit fees, the permit valuation is often lower than a market value estimate of the construction cost. In addition, many permits will have a \$0.00 valuation because the jurisdiction used some method other than valuation to determine fees, and so the jurisdiction did not log the actual valuation estimate for the permit in question. (This is very common with electrical, plumbing, and mechanical permits).
- 7. **Evaluate Risk and Mitigation:** BuildFax also provides an analysis of particular risk and risk-mitigating keywords within permit data to flag permits that may be of interest to BuildFax customers. BuildFax analysts have combed through more than 80 million permits with a state-of-the-art text mining engine to come up with the particular risk keyword categories provided on the "risk" tab. Like the "major systems" analysis, the "risk" analysis is imperfect, although usually accurate.
- Take Note of the Contractors: The "contractors" tab lists all of the contractors who have done work on the above address in the jurisdiction's database, along with details about the contractor's activity in the local jurisdiction. For example, you can see how many permits the contractor has pulled in the jurisdiction over a particular date range.
- 9. **Review the Permit Details:** The "permits" tab lists all of the permits that make up the rest of the Structure PROFILE report. After reviewing major systems, value changes, risk, and contractors, the "permits" tab shows you the full details of all permits over time for the above address.
- 10. **Follow Up:** The jurisdiction listed on the "summary" tab and the contractors listed on the "contractors" tab are great resources in understanding the permits that have been issued on the above address. If you have questions about particular key words in permit details, or about permitted work in general, BuildFax strongly recommends that you contact the jurisdiction and/or the relevant licensed contractors to find out more.

BY EVALUATING THE DATA CONTAINED ON THE SITE, THE EVALUATING PARTY AGREES TO BE BOUND BY THE TERMS OF USE AND ACKNOWLEDGES THAT SUCH AGREEMENT CONSTITUTES A BINDING CONTRACT BETWEEN THE EVALUATING PARTY AND BUILDERADIUS, DBA BuildFax.com.

Report Serial Number: 20101210102450566872-MVZRAK-258649



The data displayed here represents only that which has been received in digital format from available data source(s), and may not represent the totality of all data associated with searched properties. BuildFass is not responsible for omissions or inaccuracies. Information unavailable in digital format will not be represented.

Report Generated on 10th December 2010 10:24AM EST